


嘉義縣信義國小(CHY013)


TM2

174902.0000 2584107.0000


SPT-N




S-Wave (m/sec)



P-Wave (m/sec)





- 1.測站緊鄰圍牆邊.
- 2.鑽孔距測站約2.5米.
- 3.測站附近無破壞,裂縫現象.