


台南縣苓和國小(CHY016)


TM2

163397.0000 2568998.0000



SPT-N




S-Wave (m/sec)



P-Wave (m/sec)





- 1.測站在禮堂南側.
- 2.鑽孔距測站約兩米.
- 3.測站附近無破壞,裂縫現象.