

台南縣玉湖國小(CHY056)





TM2


161088.0000 2573776.0000

SPT-N

S-Wave (m/sec)

P-Wave (m/sec)





- 1.測站在近大門口左側的花園裡面.
- 2.鑽孔距測站約3米.
- 3.測站附近無破壞,裂縫現象.